SERVICE BULLETIN



No. : 0IVL20050039 Date : 2005-11-28

	Model		Factory	Factory Model	Suffix	Model N	lo.	Factory	Factory Mode	el Suffix	Model N	0.
			EKHQ	32LP1DC-UA	ALUSL	V 32LP1D	С	ENMX	32LP1DC-UA	ALUSL\	32LP1D0	С
			EKHQ	32LX3DC-UA	ALUSL	V 32LX3D	C-UA	ENMX	32LX3DC-UA	ALUSLL	32LX3D	С
Model		ENMX	32LX3DC-UA	ALUSL	V 32LX3D	С	EKHQ	32LX3DCS-U	A ALUSL\	32LX3D	CS-UA	
			ENMX	32LX3DCS-UA	ALUSLI	L 32LX3D	CS	ENMX	32LX3DCS-U	A ALUSL\	32LX3D	CS
			ENMX	32LX3DCS-UA	APUSL	T 32LX3D	CS					
	Buyer		Buyer N	lame Buyer Coc		yer Name EAI	Buyer C		Buyer Name I	Buyer Code	9	
EFFECTIVE COOF 11 OF FEFFETIVE FROM SERVING STATE OF												
DATE		-	2005-	EFFECT	FFECTIVE FROM(SERIAL NO.) All of range.							
	Subject		32LP1DC-UA, 32LX3DC/S-UA Component Image Distortion Improvement									
No.	Loc No.		В	Before Change			After Cha		ange	Note	K-Code	Remark
140.		P	art No	DESC./SPEC.		Par	t No	DE	SC./SPEC.	11016	IX Oodc	Roman
Reason Of Change												
# Problem : After 20~30 min of heat run , component image has distortion in position or size. Sometimes image is shifted or duplicated . The distortion can be induced after changing the resolutions on component mode. Once image distortion is induced, all input image have distortion.												

Model : 32LP1DC-UA, 32LX3DC-UA, 32LX3DCS-UA

Cause : IIC data between ADC and CPU are corrupted by the lack of IIC Setup/Hold time.

Corrective action : Change the chip capacitor of IIC from 330pF to 470 pF \$(\$ 0CH5471K416, C1310 on Top-side of Digital PCB Ass'y)

1 /

32LX3DC_Component_Image_Distortion_SVC_Guide.pdf

** FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

	NOTE(**) : II	KEY-WORD CODE		
	Parts Set			
А	Original Early	Original or new parts may be used in early or late production sets.	To improve performance	
	New Late	Use original parts until exhausted, then stock new parts.	2. To improve productivity	
В	Original Early	Original parts may be used in early production sets only. New parts may be used in early or late production sets.	3. To improve reliability	
	New Late	Use original parts where possible, then stock new parts.	Change of material or dimension	
С	Original Early	New parts only may be used in early or late production sets.	5. Addition	
	New Late	Stock new parts.	6. Deletion	
D	Original Early	Original parts only may be used in early production sets. New parts may be used in late production sets only.	7. Correction	
	New Late	Stock original and new parts.		

CHIEF ENGINEER , approved Factory.